

Machinery.

ENGINEERING EDITION.

Index to Vol. XI.

September, 1904, to August, 1905.

1905.

THE INDUSTRIAL PRESS.

66 WEST BROADWAY,
NEW YORK.

Index to Volume XI.

Acetylene Gas as an Explosive	531	Automatic Gear Cutting Machine, An	578	Bending Stresses in Wire Ropes	426	Bronze, A Finishing Boring Bar for	654
Acid for Etching High-Speed Steel. (H. & W., 57)	656	Automatic Prick Punch with Adjustment, Otis D. Storer	381	Benjamin, C. H.: The Bursting Strength of Wooden Pulleys	613	Bronzes, Characteristics of	312
Acid Hardening Bath. "I. W. Antano"	655	Automatic Twist Drill Grinding Machine	511	Bevel Curve, Solution of the	93	Bronze Yellow Brass, To. I. W. Antano	605
Acme Taps in Sets	268	Auto-meter for Automobiles	139	Charles Clonkey	93	Brooks, Wm. H.: A Handy Tool for Locating and Aligning Shafting and Machinery	76
Adams-Farwell Automobile	131	Auto-meter, The Warner	362	Bicycle Ball Stopped a Train, How a	582	Bruised Threads, To Straighten	389
Adams, John D. Elliptical Chuck	413	Automobile Record, A High-speed	311	Bierbach, A. F.: Lubricating Soap for Wire Drawing, Screw Cutting and Working Metals	444	Brooks, W. J.: Flexible Curves for Draftsmen	497
Three-Piece Ellipsograph Again	491	Automobiles, Auto-meter for	139	Bierbaum, C. H.: Oil Grooves and the Fitting up of Bearings	459	Brutsche, A. J.: Method of Boring and Turning Cast Iron Bushing in Halves	275
Three-Piece Ellipsograph Link Motion for Rotating a Shaft 180 Degrees	214	Automobiles, Experiments with	258	Birnstock, W. W.: Filler for Defective Castings	331	Buchet, E. J.: How the Pillow-block Seat of a Large Engine was Planed Out with a Small Planer	218
One-Turn Clutch	598	Automobile Show, The	320	Birrell, Edwin M.: Pattern Shop of the U. S. Naval Gun Factory	241	Modern Work with Ancient Tools	649
Adding Attachment for the Typewriter	371	"Autopyrophon," The	203	Blacken Brass for Templet Work and Other Purposes, To. P. H. Oto	495	Buffing Wheels, Exhausting Arrangement for	475
Adjustable Boring Tool. F. A. Hobbs	551	Babbitt Crossheads, To. J. V. N. Cheney	442	Blacken Brasswork for Instruments, To. Jos. M. Stabel	655	Building Construction, Steel Cage	640
Advertising Scheme, An. R. Earl Weinland	547	Babbitt Metal or Lead from Exploding, To Prevent. R. B. Casey	605	Blackening Brass. F. H. Jackson	444	Bullard 36-inch Vertical Turbine Lathe	367
Advice to Apprentices. John Mark May	434	Bachmann, H. J.: Wire Straightener	151	Black Marks on Graduated Surfaces, To Make. F. H. Jackson	655	Bullard Machine Co., Method of Finishing Gears at	16
Aeroplane and Flying Machine, The	88	Cement for Sticking Leather Fillet on Brass Patterns	331	Black Powder, Report on by Chief Mason of Bureau of Ordnance	472	Burbank, L. S.: Table of Spur Gear Teeth Giving Diametral Pitch Mixture for Making a Porous Casting Air and Water Tight	444
Air Compressor with Minimum Clearance Space	481	A System of Drill Jigs for Rough Castings	209	Blackwell's Island Bridge, N. Y., Pins Used in the New	530	Burnishing Ball Cases on Internal Bearings, Method for	384
Air-lubricated Journal	52	Regarding Accuracy of Jigs	330	Blake, C. F.: More Notes on Band Brake Design	344	Burns, Charles E.: Improvised Vertical Milling Machine	323
Air Pump, Westinghouse Compound	640	Punch and Lie Adjustable to Cut Sectors of Various Lengths	387	Beams and Planes with Several Supports	68	Bursting of Four-foot Flywheels, The	261
Albespeyre Tunnel, The Ventilator of the. Dr. Alfred Gradenwitz	32	Milling and Drilling Jig	595	Blake (W. H.) Condenser, The	500b	Bursting Strength of Wooden Pulleys, The. C. H. Benjamin	613
Alcohol as a Source of Power	641	Balancing Arrangement for the Rams of Boring Mills	202	Blanking and Forming Dies. V. H. Marcellus	649	Bushings for Drilling and Reaming Jigs. O. C. Bornholt	491
Alcohol Motor in France, The Allen, Leicester	318	Balancing Centrifugal Pumps	586	Bliss Press with Special Feed	644		
Some Faults of Indexing	353	Balancing High-Speed Gasoline Engine	498	Bluing from Tempered Steel, To Remove. F. H. Jackson	605	Calculating Charts	425
Allis-Chalmers Shops, Spherical Boring and Turning in the	574	Balancing Moving Parts	524	Bluing Small Brass and Steel Articles by Immersion, For. L. E. Muncy	605	Caliber the Fit of a Screw Thread. H. E. Wood	275
Alloy of Aluminum, Copper, and Manganese	577	Ball and Roller Bearings, Carrying Capacity of (How and Why 11)	107	Blue-prints	54	Camera, A Sketching. Warren E. Willis	326
Aluminum for Bedplates and Other Castings	222	Ball-bearing Rifle Gun	32	Bluff that Went, "A. A. P. Press"	601	Cammie Screw Machines for Thread Cutting, G. H.	388
Aluminum, Fusing and Molding of	107	Ball Bearings	329	Bog Fuel, The Possibilities of	256	Cam, The Davis Self-Locking	44
Aluminum Patterns, Soldering	627	Ball Cases on Internal Bearings, Method for Burnishing	384	Bog Explosion	657	Carborundum Wheels, Ezra F. Landis	102
Alternators of the N. Y. Subway, Engine-driven	533	Ball, M. H.: Prick Punch Holder	160	Bolter, Large Water Space Watertube	263	Car Inspectors are Beaten, How	40
Aluminum, Making Castings in	35	A Finishing Boring Bar for Bronze	654	Bolter Plate Ever Rolled, Largest	257	Carnegie Engineering Building, Plans for the	137
Aluminum, Soldering. R. Earl Weinland	494	Band Brake Design, More Notes on. C. F. Blake	344	Bolter Shell Chart	68	Carpet Tack, New	33
Aluminum, Something about. Earl N. Percy	413	Bandsaw in the Machine Shop, The	85	Bolter Tube, A Spirally Corrugated	86	Carriage Stop for Lathe. J. A. Webster	383
Amalgam for Stopping Leaks, Blowholes, etc. O. M. Becker	655	Bandsaws, Cold-soldering	202	Borax, Process for Pulverizing. Albert D. Knael	444	Carrying Capacity of Ball and Roller Bearings (How and Why 11)	107
American Blower Co.'s New Engine, The	309	Bardons & Oliver Lathe, A Large	13	Boring and Turning a Cast Iron Bushing in Halves, Method of	275	Calcium Reduced by Electrolysis	533
American Industries, German View of	370	Bar Holder, Facing. B. M. Weller	269	Boring Bar for Chasing Threads	153	Car Wheel Press, Handy Water Connection for. A. E. Mitchell	443
American Machine Exports to Germany	403	Barnard, Wm. N.: Strength of Beams with Ribbed Sections, a Paradox	176	Boring Bar Holder	159	Car Wheels, Rolled Steel	427
Ammonia on Iron, Effect of	390	Barney: Catching Threads and Gaging the Depth	152	Boring Bar, Radial Attachment for. D. Lindsay	330	Casehardening	642
Angle Bars, Method of Bending	34	Barnitt, Correction in Name	475	Boring Brasses, Fixture for. Philadelphia	159	Case-hardening Cast Iron. A. Hayes	605
"Angle of Pressure" of Spur Gears	331	Bath Universal Grinding Machine, New	360	Boring, Facing and Turning Small Spur Gears, Appliances for. "Jaymac"	650	Case-hardening Preparation, Formula for. James P. Hayes	391
Angle of V-Tool to Plane Notches, etc. (H. & W., 52)	606	Baxter, Jr., William: Variable Speed Motors	26	Boring Mill, A Ridgway 10-16 Foot, The First Tool Produced	407	Casey, R. B.: Mixture for Plugging Holes in Cast Iron	495
Angles from a Table of Tangents, To lay out	220	120, 171, 246, 348, 399, 513		Boring Rotary Pump Casing, Tool for. L. Myers	440	To Recut Old Files	391
Anisometric Projection. Robt. Grimshaw	492	Beale, Oscar J.: To Copper Brass for Laying Out Work	605	Boring Taper Holes in Lathe Tail Spindles. E. H. Fish	651	How a Triple Worm was Cut	220
"Antano, I. W." To Bronze Yellow Brass	605	"Beams and Planes Eccentrically Loaded." E. E. Graham	175	Boring Tool, Adjustable. F. A. Hobbs	551	To Prevent Babbitt Metal or Lead from Exploding	605
Acid Hardening Bath	655	Beams and Planes with Several Supports. E. E. Graham	29	Bornholt, O. C.: Bushings for Drilling and Reaming Jigs	491	Cast Iron Bushing in Halves, Method of Boring and Turning. A. J. Brutsche	275
Anvil Block, Improved. J. H. DeGroodt	379	John S. Myers	30	"Boston Tool" for Model Work	277	Castings in Aluminum, Making	35
Application of Motors to Machine Tools	372	"C. F. Blake"	68	Bouvier Governor for Water Turbines. Dr. Alfred Gradenwitz	523	Cast Iron Sinks	158
Apprentice, A Successful	99	Beams, Graphical Solution for	214	Boy Electricians	267	Cast-iron Spring Piston Ring, Proportions for a (H. & W. 38)	445
Apprentices, Advice to. John Mark May	434	Beams with Ribbed Sections, Strength of — A Paradox. Wm. N. Barnard	176	Brains are His Own, A Man's Brass Railings, Cost of Polishing	297	Cast Iron, to Harden—To Keep Water from Freezing or Souring. W. T. Sears	444
Apprenticeship Question, The. Prof. John E. Sweet	52	To Mend Broken Oil Stones	442	Brass, Silver, Paste for. J. S. Gordon	391	Catching Threads and Gaging the Depth. Barney	152
Armature, Rewinding of	486	Amalgam for Stopping Leaks, Blowholes, etc.	655	Brass Wire in Brazing, The Use of. F. H. Jackson	605	Catgut	638
Armstrong Bros. Shops, Making Inserted Cutters in	631	Bedplates and Other Castings, Aluminum for	222	Brasswork for Instruments, To Blacken. J. M. Stabel	655	Cement for Holes and Cracks in Castings. C. E. Mink	605
Arras, C. C. Prick Punch with Interchangeable Scriber Points	604	Bell, A. R.: Iron and Its Early Manufacture in England	185	Brass Work, Frosting. F. H. Jackson	495	Cement for Metals. H. S. Gladfelter	655
Arthur, James. A Five Minute Repeater Clock	339	Bells, Old Formula for	421	Bridge Building since 1880	86	Cement for Iron. David Melville	605
Friction of Sliding Keyways	218	Bells, The Designing and Making of. F. P. Lotz	295	Bridge Over St. Lawrence River, Steel	585	Cement for Slicking Leather Fillet on Brass Patterns. H. J. Bachmann	331
"Standard" Nose Threads for Lathe Spindles	95	Belt, Improved Method of Allowing for a Slack	371	Bristol: Loose Pulleys	490	Cement for Steam Pipes, Permanent Iron. J. H. Taylor	495
Artisans—5th Annual Session, Summer School for	475	Belting	537	Bristol, F. B. (Obituary)	184	Cement, Novel Use of	648
Asbestos, Applying. James A. Pratt	604	Belts, Lacing	276	British Industrial Methods, Reorganization of	294	"Center-Pressure" Stop Valve	434
Ash, Harry. Coloring Steel	391	Bench Vise, Quick-action	83	British Patent Laws, Stricter	140	Centrifugal Pumps, Balancing	586
To Mottle Casehardened Pieces	331	Bending Angle Bars, Method of	34				
Ashley, Carroll. An Experiment with Gas	381	Bending Angles and Structural Shapes. Frank B. Kleinhans	306				
A Leather Medal	150	Bending Cast Iron Pipe	94				
A. S. M. E., Annual Meeting of the	236	Bending Dies, Some Hints on	273				
A. S. M. E., June Meeting of the	545	Bending Fixtures for Two Operations, Set of	325				
A. S. M. E., Scranton Meeting of the	593						

Centrifugal Pumps for Elevator Service, Multi-Stage	583	Construction, Steel-concrete.	86	Death of Mr. George A. Gray.	567	Drop Hammers for Pile Drivers, Superiority of.	139
Chain Drive in a Rubber Mill	136	Consumption of Steel Increased.	477	Deep Mine Hoisting Engines.	201	Dry Air System, Gayley.	534
Chain, Manufacture of.	318	Contest Between Guns and Armor.	638	Defective Castings, Filler for.	331	Durfee, Frederic E.	
Change Gear Device, Proposed.	48	Cooking Stoves, Fireless.	637	Definitions of Early Writers.	573	Rules for Figuring the Speed of Pulleys and Gears.	597
Change Gears for Diametral Pitch Worm Teeth, John T. Giddings.	153	Coolgardie Pipe Line, Construction of the.	403	De Forest Wireless Ship Localizer.	290	Dust Laid by Oil or Calcium Chloride.	86
Changes of Lead Due to Hardening, Lathe Gearing Compensation for.	436	Copper Alloyed with Iron.	67	"Defries" Precision Lathe, The, Dr. Alfred Gradenwitz.	147	Dynamo, A Commercial Unipolar.	375
Chart for Hollow and Solid Shafts.	148	Copper Brass for Laying Out Work, To, O. J. Beale.	605	De Groodt, J. H.		East Boston Tunnel, New.	369
Charts, Calculating.	425	"Copper Floats."	251	Improved Anvil Block.	379	Eccentric Loading, Frank B. Kleinbans.	30
Charts for Forming Tools, Geo. D. Hayden.	103	Copper on Old Whalers.	33	De Laval Steam Turbine and Its Manufacture.	123	"Eccentric Loading," Correction of a Calculation in.	354
"Charts for Forming Tools," Error in.	130	Copper Solution that Will Color on Oily Steel.	655	De Laval Steam Turbine Co., The.	61	Economizer, Sturtevant.	106
Charts in Designing, John S. Myers:		Copper-Wire, Hard-drawn.	430	De Leeuw, A. L.		Economy in Different Sizes of Coal, Relative.	402
(1) Thickness of Cylinders	9	Copying Printed Pictures, A Process for, Joseph C. Riley.	5	High Speed Planers.	501	Eckelt, Otto:	
(2) Helical Springs.	145	"Core and Coil" Problem, The	545	Generating a Large Index Plate.	621	To Measure the Radial of Deep-hole Drills.	298
(3) Helical Springs.	145	Core Box from the Pattern, Making a, Julian D. Page	158	Simple Solution of Question No. 55.	656	Education, Contemporary Technical.	245
Chasing Threads, Boring Bar for, D. Lindsay.	153	Correction, A—Table of Spur Gear Teeth Giving Diametral Pitch.	383	Derf, R. E.		Effect of Oil on Portland Cement.	545
Checking a Drawing, Julian E. Page.	382	Correction in August Data Sheet.	33	Simple Gear Cutting Device.	388	Effect of Traction Wheels of Electric Motor Cars.	604
Cheney, J. V. N.:		Correction in Name, Barnitt.	475	Designing and Making of Bells, The, F. P. Lotz.	295	Efficiencies of Various Kinds of Gears.	565
To Babbitt Crossheads.	442	Correction of a Calculation in "Eccentric Loading," F. B. Kleinbans.	354	Designing, Charts in, John S. Myers:		Electrically Driven Sand Mixer.	500a
To Heat the Tips of Small Tools.	391	Correction of February Data Sheet.	389	(1) Thickness of Cylinders.	9	Electrical Repair Job, An, "Jaymac."	652
Chern, A. R.:		Corrugated Grinding Wheel, The.	500a	(2) Helical Springs.	145	Electric Cables, New Method of Laying.	311
Device for Preventing wear of Shaper Tools.	98	"Corubin," Resistance of.	122	(3) Helical Springs.	145	Electricity for Heavy Railway Operations, Use of.	533
Chimney, A 182-foot Concrete	311	Cost, How Much Does it.	584	Diametral Pitch, Worm Teeth, Change Gears for, J. T. Giddings.	153	Electricity Produced from Burning Refuse.	423
Chimney, How to Fall Down a	389	Cost of Cutting by Emery Wheels and by Filing, Relative.	141	Diamond Drill Borings in the Transvaal.	533	Electric Locomotive, Trial.	176
Chimneys Built from a Derrick.	139	Cost of Increased Rapid Transit Facilities in New York.	139	Diamond Tools.	260	Electric Motor Drive in the Naval Gun Factory.	351
Chuck, An Expansion, J. M. Stabel.	549	Cost of High Speed Steel.	230	Die, Combination Forming, W. Van Orman.	438	Electric Motors in Steel Mills.	544
Chuck, Elliptical, John D. Adams.	413	Cost of Polishing Brass Railings.	297	Die, A Combined Cutting, Drawing and Knurling, C. F. Emerson.	275	Electric Motor Versus the Steam Engine, The.	312
Chuck for Holding End Mills, L. E. Muncey.	105	Cost of Power in Street Railway Service.	317	Dies, Blanking and Forming, V. H. Marcellus.	649	Electric Motors.	638
Chucking Fixture, P. A. R. Chuck Jaws, To True Universal, J. E. Manierre.	214	Counterbalancing an Oscillating Engine.	632	Dies for Making Tin Nozzles, Practical.	487	Electric Plants for London and Suburbs.	643
Chuck Plates, Patterns for, E. H. Fish.	51	Counterbore, Special, W. C. Force.	652	Dies, Making Drop Forging, C. W. Shelly.	266	Electric Power First Generated at Niagara.	309
Chucks, Time-saving, A. Merces.	95	Covering Pulleys with Leather, C. E. Mink.	596	Dies, Some Hints on Bending.	273	Electric Repairing, Norman G. Meade:	
Circuit Breaker with Solenoid Attachment, Herbert S. Gladfelter.	597	Cracks in Castings, To Repair.	311	Differential Gearing, Some Cases of, A. B.	74	(1) The Commutator.	187
Civilized, Though Savage.	389	Crane Co., Fiftieth Anniversary of.	620	Differential Indexing, Formulas for, J. O. Villars.	154	(2) Armature Winding.	249
Clamp Coupling in Cement Mills, The Advantage of the, H. A. Houghton.	214	Crane Motors, Calculations for the Shaft, Gear and Bearings of, G. J. Leire.	565	Dimensions of Ells and Tees for Wrought Iron Pipe, W. J. Mann.	529	(3) Armature Coils.	307
Cleaning Tenders, Sand Blast Apparatus for.	89	Crane Motor Testing Apparatus.	541	Diploma, A Jap.	136	Electric Sign, The Largest.	311
Cleaning, Vacuum System of Clock, A Five-Minute Repeater, James Arthur.	339	Crematory in New York City with Electric Lighting Plant, Experiment for.	423	Dirt from Clean (?) Floors, Disch, Theodore.	201	Electric Welding.	585
Clock, Handless.	33	Criticism, A. E. Kwartz.	602	Insulating Covering for Steam Pipes and Boilers.	444	Elementary Principles, Importance of.	256
Clocky, Charles:		Criticism, A friendly.	532	Pulley Crowning Device.	491	Elliott, H. D.:	
Solution of the Bevel Curve Clutching and Speed Accelerating Device of the Cutter-Hammer Mfg. Co.	468	Crown Brasses, Tool for Laying out, R. G. D.	219	Distance between two Ells Connecting two Parallel Lines of Pipe, Method of Finding.	319	Feed Relief for Planer Under Cutting Tool.	654
Clutch, One-Turn, J. D. Adams.	598	Crossheads, To Babbitt, J. V. N. Cheney.	442	Distinctive Colors, The Use of, Oscar E. Perrigo.	364	Ellipses, Lathe for Turning Ellipsograph Again, Three-Piece, John D. Adams.	491
Clutch Shifter, Magnetic, Herbert S. Gladfelter.	271	Crown Gear Defined (How and Why, 35).	390	Distortion of Automobile Wheels in Photographs.	25	Ellipsograph, Three-Piece, J. D. Adams.	151
Clutch Teeth, Milling Square Jaw, Draftsman.	221	Crucible Steel for Turning and Planing Tools, etc., J. M. Gledhill, of Armstrong, Whitworth & Co.	423	Double-Head Tool for Plate Planers, Toolmaker.	443	Ellipsograph, Three-piece, A Criticism, Charles G. Taylor.	386
Coal, Relative Economy in Different Sizes of.	402	Crude Oil to Generate Electricity.	398	Draft Fan, Large Mechanical, Draft Gage, Improved.	55	Elliptical Chuck, John D. Adams.	413
Coal, Statistics of the World's Output of.	467	Crushed Coal for Locomotives.	86	Drafting Kink, A. E. H. Fish.	104	Elliptic Curves, Simple Device for Drawing.	496
Coat Zinc Sheet Black for Templet Work, To, Alex. C. Labar.	331	Cunard Turbine Steamers.	70	Drafting Room Practice, Ralph E. Flanders.	355	Emergency Repair Jobs.	636
Cocoa, Wonderful Power of.	615	Cunard Vessel, New.	139	Draftsman.		Emerson, C. F.:	
Coffee Mill, Construction of an Old, H. Jonson.	653	Custodis Brick Chimney, A.	130	Milling Square Jaw Clutch Teeth.	221	A Combined Cutting, Drawing and Knurling Die.	275
Coil-clutch Reversing Gear.	423	Cutter Construction, Inserted Blade, H. D.	549	Lathe Rig for Turning Machine Handles.	217	Planer Bar with Stiff Support.	96
Coiled Spring Mounted on a Mandrel, Advantages of.	423	Cutting and Applying Gaskets, J. A. Pratt.	494	Draftsman's Competition, A Novel.	310	Making Redrawing Dies Economically.	436
Cold-soldering Bandsaws.	202	Cutting, Drawing and Knurling Die, A Combined, C. F. Emerson.	275	Draftsman's Number of Machinery (September).	532	Don't Use Lard Oil on Machinery.	653
Cold Tinning Process for Use on Finished Work in Iron, Brass or Steel, J. L. Lucas.	655	Cutting English Threads with Metric Leadscrew, A. L. Valentine.	440	Drawing Board, Parallel Motion for, H. M. B.	215	Emerson, F.:	
College Engineering Courses, Increase of Students Taking.	423	Cutting Multiple Threaded Screws, John T. Giddings.	153	Drawing D. C. Colls, Directions for, Oscar Stegeman.	174	Mortar for Stopping Holes in Boiler Settings, etc.	655
Coloring Steel, Harry Ash.	391	Cutting Multiple Threads with a Chaser, T. E. Remington.	330	Drawing Table, Improved, Geo. Washington.	437	Emery for Fine Lapping, To Prepare, J. M. Stabel.	494
Colors, The Use of Distinctive, Oscar E. Perrigo.	364	Cutting off Stock in Engine Lathes, Herman Jonson.	221	Drawing Table and Bookstand for Traveling Mechanics, J. H. A.	324	Emery Wheels, Experimental Work on Solid.	204
Columns, The Strength of.	428	Cutting Threads on a Metric Lathe, English System.	330	Drill Breakage, To Reduce Small, Park B. Shee.	494	Emery Wheels to Rupture, The Resistance of.	35
Colvin, Fred H.:		Cutting Tools and Application to Lathe Design, Experiments with.	481	Drilling and Reaming Dies, Bushings for, O. C. Bornholt.	491	Employees, Subway.	53
The Practical Perspective Combination Forming Die, W. Van Orman.	438	Cutting Tabs on Index Cards (How and Why, 60).	657	Drilling Hard Steel, Solution for, C. E. Mink.	495	Employees at Panama, Regulations for.	422
Commutators in which the Mica Insulation has Burned Away, Repairing.	645	Cylinder Grinder, Heald.	644	Drilling Holes, Practice in (How and Why, 45).	498	Energy Expended in the Production of Light.	637
Comparisons and Notes on Prime Movers.	313	Dahlstrand, Hans.		Drill Jigs for Rough Castings, A System of, H. J. Bachmann.	209	Engine Beds, Planing, F. H. J.	442
Compressed Air as an Aid to Fan Blast in Forge Shop, A. E. Mitchell.	437	Lathe Gearing Compensation for Changes of Lead due to Hardening.	436	Drill Jigs, Method for Making, N. J. W.	383	Engine-driven Alternators of the N. Y. Subway.	533
Compressed Air, Water Pressure Maintained by.	171	Dall, C. M.		Drill Press Attachment, A Novel, J. V. Woodworth.	490	Engineer as a Business Man, The.	34
Compression Space in a Gas Engine Cylinder (How and Why 14).	161	Self-aligning Holder for Screw Machine.	388	Drills, Experiments with High-Speed Steel.	259	Engineering Courses, Increase in, Prof. W. G. Raymond.	423
Concrete Construction, Great Strength of.	140	Damascus Steel a Form of High Speed Steel.	257	Drill Speeds Table.	148	Engineering Standards, Working Toward.	137
Concrete for Setting Posts, Advantages of Using.	201	Danger of Oil in Boiler Furnaces.	533	Drilling Boxes, Device for Lifting, I. C. Hicks.	105	Engines for U. S. Armored Cruisers Nos. 6 and 9, the California and South Dakota, Earl N. Percy.	198
Concrete Piles, Run Forced.	368	Dangerous State of Streets in our Large Cities.	639	Drop Forging Dies for Conper Shrinkage Allowance in (How and Why, 43).	498	Engines at Nashville, Tenn., Old.	477
Concrete, Proportions and Character of Sand and Gravel to Use in.	530	Data Sheet, Correction in August.	33	Drop Forging Dies, Making, C. W. Shelly.	266	Engines, Old Pair in Use Since 1844.	477
Concrete, Reinforced.	588	Data Sheet Errata, January.	318			Engine, The American Blower Co.'s New.	309
Condensation Fallacies and Facts.	38	Data Sheet for November.	119			English High-Speed Planer, An.	576
Condensers for Steam Turbines.	260	Data Sheet for September, The.	25			English Lathes, Some, James Vose.	21
Connecticut Still Safe, The.	138	Davis, Frank M.				English Threads, Cutting with Metric Leadscrew, A. L. Valentine.	439
Connecting Shafts (How and Why 8).	107	Repairing a 400-Ton Hydraulic Press.	630			Epicyclic Gearing, Solution of Problem in (How and Why, 39).	445
		Davis Self-Locking Cam, The.	44			Epochs in Marine Engineering.	378

Erratum	545	Fixture for Boring Brasses. Philadelphia	159	Glue for Leather Belts. L. E. Muncy	495	Heating Baths for Use in Steel Hardening. Robert Grimshaw	599
Error Corrected: Steel Hardening and Tempering Compound. W. S. Hindman, Columbus, Ga.	528	Flanders, Ralph E.: A Sectional Fixture	93	Glue, Formula for Insoluble. Gold from Sea Water.....	201	Heating Surface of a De Glehn Locomotive	85
Error Corrected in Table of Spur Gear Teeth Giving Diametral Pitch	276	On the Shape of Rolls for Cylinder Cams	209	Gold Welding	107	Heat Question as Affecting the Accuracy of Machine's Operation. Something on the McAnic	549
Error in Charts for Forming Tools	130	Drafting Room Practice... An Ingenious Mechanical Movement	355	Gordon, J. R.: The Grinding of Thread Gages	78	Heat the Tips of Small Tools. To J. V. N. Cheney	391
Essen and the Krupp Works Estimating Cost, with Examples Illustrating Application of Method. James A. Pratt	71	Flexible Curves for Draftsmen. W. J. Brooks.....	497	Accurate Jig Making	156	Heavily Loaded Bearings, High-Pressure Oiling System for	236
Estimating the Cost of Machine Work. J. A. Webster	569	Flexible Staybolt Problem... Flying Machine, The Aeroplane and	583	Accurate Jig Making..... Lathe Attachment for Turning Trolley Wheels	328	Heavy Fluids, Pumping	236
Etching Fluid. L. Melville	605	Flywheels on Board Ship, Gyroscopic Effect of	88	Silver Paste for Brass... Gould, Stanley: Rig for Re-turning Piston Rings	391	Helical Gears, Constructing a Train of (How and Why 48)	406
Etching Solution. L. Meyers	444	Flywheels, The Bursting of Four-foot	477	Gould, W. E.: Milling Flat Forming Cutters	488	Helical Springs, Tests of... Henderson, R. H.: Tool Steel Forging and Tempering	552
Ethics of Contributions.....	584	Fog-makers, Locomotives as "Fool proof" Engine, A.....	261	Governing Under High Heads, Sensitive	602	Hicks, I. C.: Device for Lifting Driving Boxes	624
Evaporation, Multiple-Effect	427	Forced Draft Instead of Induced Draft, Use of.....	77	Gradenwitz, Dr. Alfred: The Ventilator of the Albespyre Tunnel	86	High Carbon Steel	67
Exhausting Arrangement for Buffing Wheels	475	Forced Grease Lubrication System	533	The "Defries" Precision Lathe	32	High-Pressure Oiling System for Heavily Loaded Bearings	105
Expanding Nozzle in De Laval Steam Turbine	54	Forced Lubrication, Increase of Efficiency by	482	An Experimental Gas Turbine	147	High-Speed Automobile Record, A	638
Expansion Chuck, An. J. M. Stabel	549	Force, W. C.: Special Counterbore	193	A Novel Process for Testing Lubricants.....	169	High-Speed Gasoline Engine, Balancing (How and Why 44)	236
Expansion Chuck for the Vertical Mill, An. Uncle Josh	380	Foreman: "The Man Who is the Whole Thing"	652	The Bouvier Governor for Water Turbines	415	High-Speed Machinery Notes Upon Balancing	311
Expansion of Cast and Tool Steel Respectively (How and Why 37)	445	"The Man Who is the Whole Thing"	321	The Graduated Surfaces, To Make Black Marks on. F. H. Jackson	523	High-Speed Planer, An English	498
Experimental Gas Turbine, An. Dr. Alfred Gradenwitz	169	Forging and Tempering, Tool Steel. R. H. Henderson	67	Graduating for Degrees in the Index Head. C. J. Shaw	655	High-Speed Planers. A. L. De Leeuw	183
Experiments with Non-magnetic Metals to Form Alloys	423	Formed Cutters on the Lathe, Making. Charles Thiel	216	Graham, E. E.: Beams and Planes with Several Supports	442	High-Speed Pumps, The Gutterth Valves for	576
Explosion, Boiler	657	Forming Die, Combination. W. Van Orman	438	Beams and Planes Eccentrically Loaded	29	High-Speed Steel, Cost of	478
Explosions of Gasoline and Other Inflammable Liquids, Device for Preventing.....	87	Forming Dies, Striking Up. Pedro Re	384	Grant's Receipt for White-wash, W. E. G.	175	High-Speed Steel, Tests on	230
Explosive, Acetylene Gas as an	531	Forming Tools, Charts for. George L. Hayden	103	Gray, Leath of Mr. George A. Great Britain, Germany and America, Invention in	391	High-Speed Steel Drills, Experiments with	259
Eye Inflamed by Emery Wheel Sparks, To Avoid and Cure (How and Why 30)	231	Jigs and Milling Fixtures with Operation Sheet... Foundry Micrometer for Test Bars	265	Greenwood Colliery Fire, The Grimshaw, Robert: German Lathe Carriage for Screw Cutting	567	High-Speed Steel Razors.....	46
Eye Surgery, Simple	119	Frictional Gearing, Power Transmission by (How and Why 22)	321	Grimshaw, Robert: German Lathe Carriage for Screw Cutting	79	High-Speed Steel, The Uses of. G. H. B.	256
Facing Bar Holder, B. M. Weller	269	Friction Disk Drives, Design of (How and Why 58)	222	Anisometric Projection	492	High-Speed Tools, The Development and Use of	420
Facing Segment Gears	221	"Friction of Sliding Keyways." James Arthur	656	Micrometer Gage for Milling Cutters	443	High Temperature on the Strength of Steel, Effect of	194
Facing Valve Seats Without Removing the Pistons	370	Friction of Sliding Keyways	218	Triangle for Isometric Drawing	386	Hindman, H. S.: Steel Hardening and Tempering Compound.....	257
Fairfield, Howard P. Shop Training for Mechanical Engineering	517	Friction Saw, A Large	543	Heating Baths for Use in Steel Hardening	599	Historical Interest, Of	444
Failure of Iron Plate from Fatigue	658	Frosting Brass Work. F. H. Jackson	495	Grinding Machine, Automatic Twist Drill	511	Hobbs, F. A.: Adjustable Boring Tool	421
Falk, E. C.: Methods for Obtaining the Distance Between Ells to Connect Parallel Lines of Pipe	528	Furnace, A New Hardening... Furnace, The Gantt	264	Grinding Machine, New Bath Universal	360	Historic Locomotive, A	551
Fall Down a Chimney, How to	389	Fusing and Molding of Aluminum (How and Why 10)	500a	Grinding of Thread Gages, The. J. R. Gordon	78	Hoisting Engines, Deep Mine	85
Fan and Special Form of Heater, furnished by B. F. Sturtevant Co.	497	Gage Making. F. E. Shaller	546	Grinding Operation, An Interesting	623	Hoisting Machinery, Modern Steam. A. M. Levin	201
Fan Blast in Forge Shop, Compressed Air as an Aid to. A. E. Mitchell	437	Galvanizing Iron, New Sherardizing Process for	637	Gunpowder to Avert Hall-storms, Using	350	Hollow and Solid Shafts, Chart for	453
Fans vs. Positive Pressure Blowers	258	Galvanizing Process, New	33	Guns and Armor, Contest Between	638	Hollow Mill, Adjustable. V. H. Marcellus	148
Faults of Indexing, Some. Leicester Allen	353	Gang Milling of Repetition Castings. Joseph V. Woodworth	582	Guns, Enormous Pressure of Modern	647	Hollow Mills, Regarding the Teeth of. C. H. Rowe	51
Fay, W. L.: Planing Spiral Corrugated Rolls	274	Gas, An Experiment with. Carroll Ashley	381	Gutterth Valves for High-Speed Pumps, The	478	Honesty the Best Policy.....	215
Milling Cutters with Teeth Cast in	653	Gas as a Motive Power and Its Relative Cost	641	Gyroscopic Effect of Flywheels on Board Ship.....	477	Hollow Coupling	370
Feed Gear, Screw Cutting with the	104	Gas Engine Design, Frequent Mistake in	636	Hacksaw as a Parting Tool in the Lathe, Using a. Robert B. Otis	222	Hot Water for the Tin Shop. Park B. Shee	496
Feed Relief for Planer Under Cutting Tool. H. D. Elliott	654	Gas Engine Economy. George Miller	305	Hack Saw Kinks. R. A. Lachmann	604	Houghton, H. A.: The Advantage of the Clamp Coupling in Cement Mills	277
Fiberloid	55	Gas Engine Power Plant	106	Hall Storms, Using Gun Powder to Avert	350	How Can Locomotive Boiler Construction be Improved?	430
Field Coils, Repairing. N. G. Meade	529	Gas Engines on Shipboard, Producer	373	Hafner, John C.: Some English Inserted Cutter Tools	385	Hydraulic Pipe Flanges, Standard. F. B. Kleinhans	618
Figuring the Speeds of Pulleys and Gears, Rules for. F. E. Durfee	597	Gas Engine Testing	376	Hallifax Dock Yard in Nova Scotia	469	Hydraulic Press, Repairing a 400-ton. F. M. Davis	630
File a Sharp Scriber, To. R. A. Lachmann	597	Gas for Intermittent Heating, Value of	371	Hamilton - Holzworth Steam Turbine, The	134	Hydraulic Valve Improvement. W. T. Sears	270
Files by American Methods, The Making of Fine Tool-makers	431	Gaskets, Cutting and Applying. J. A. Pratt	494	Hammacher, Schlemmer & Co., New Store of	368	Iayonac: More Shop Cost Troubles	414
Filler for Defective Castings. W. W. Birnstock	331	Gas Turbine Problem, Practical Investigations in	480	Hand Taps with Standard Threads. H. D.	603	Idle Machines, Something More Regarding. A. Merces	95
Finishing Boring Bar for Bronze. A. M. H. Ball	654	Gasoline Engines for Bicycles	32	Haphazard Supplying of Coal to Locomotives	86	Improved Bumping Posts	430
Finishing Gears at the Bullard Machine Tool Co., Method of	16	Gasoline Motive Power for Suburban Traffic	371	Hard-drawn Copper Wire	430	Improvement All Along the Line	177
Fire Cement, Mixture for. C. E. Mink	605	Gasoline Motor Railway Cars	534	Harden Cast Iron, To. W. T. Sears	444	Impulse and Reaction Turbines	346
Fire Engines in Vienna, Motor-driven	533	Gas Producer Power Plants	539	Hardening Bath, Acid. I. W. Antano	655	Incarescent Lamp, A New	423
Fire Engines, Early	257	Gayley Dry Air System	534	Hardening Circular Forming Tools (How and Why 59)	656	Indelible Pencil in Photography, The	219
Fireless Cooking Stoves	637	Gear Cutting Device, Simple. R. E. Derf	388	Hardening Furnace, A New	264	Index for Machinery (1903-4)	70
Fire Protection in Marshall Field Department Store, Chicago	245	Generating a Large Index Plate. A. L. DeLeeuw	621	Paste for. J. M. Stabel	495	Index Head, Graduating for Degrees in the. C. J. Shaw	442
Fireproof Wood in Buildings Fire, The Greenwood Colliery	70	Generators, Oil-Insulated	638	Hardening of Hack Saw Blades (How and Why 50)	606	Indexing, Some Faults of. Leicester Allen	353
Fish, E. H.: Proposed Change Gear Device	48	German Fear of Publicity	586	"Hardening Work in Part." Another. C. H. A.	104	Index Plate, Generating a Large. A. L. De Leeuw	621
Patterns for Chuck Plates A Drafting Kink	104	German Manufacturers Demand Higher Tariff on Machine Tools	139	Harden Thin Saws Without Warping, To. V. H. Marcellus	494	Indicator, A Simple. J. Mathieu	277
Quick-return Shaper Motion	97	German Oil Filter	648	Hard Rubber, Alleged Discovery of the Process for Making	140	Induction of an Underground Cable as Compared with a Line Wire	371
Some Simple Red Tape	628	German View of American Industries	370	Hard Steel, Solution for Drilling. C. E. Mink	495	Industrial Methods, Reorganization of British	294
Boring Taper Holes in Lathe Tail Spindles	651	German Workmen to Sports, Indifference of	87	Hayden, George D.: Charts for Forming Tools	103	Inflamed Eyes, Remedy for (How and Why, Ans. to 30)	390
Fishing Boats, Motors on	84	Giddings, John T.: Change Gears for Diametral Pitch Worm Teeth	153	Haves, James P.: Formula for Case-Hardening Preparation	391	Ingersoll-Sergeant Drill Co., New Works of the	461
Five Levels of Transportation in New York, Proposed	88	Cutting Multiple Threaded Screws	153	Heads of Machine Screws, Notes on	589	Injured Steel, Remedy for	88
Fixture, A Sectional. Ralph E. Flanders	93	Gladfelder, Herbert S.: Magnetic Clutch Shifter	271	Head Work Greater than for Hand Work, Demand for	476	Inserted Blade Cutter Construction. H. D.	549
		Circuit Breaker with Solenoid Attachment	597	Heald Cylinder Grinder	644	Inserted Blades, Method of Securing. G. L. F.	425
		Cement for Metals	655	Heating and Ventilating Apparatus for the New Wanamaker Stores	236	Inserted Cutters in Armstrong Bros. Shops, Making	631
		Glass or Bright Metal, To Write Black on. F. H. Jackson	444				

Inserted Cutter Tools, Some English. John C. Hafner	385	Some Lathe Fixtures	101	Lifting Magnets for Handling Iron and Steel	363	Marine Engineering, Epochs in	378
Inspectors are Beaten, How Car	40	Standard Hydraulic Pipe Flanges	618	Lifting Magnet, New	594	Marine Propeller Wheels, Direction of Rotation of	137
Insulating Covering for Steam Pipes and Boilers. Theodore Birsch	444	Knave, Albert D.: Process for Pulverizing Borax	444	Lightening Conductors, On. Lindmark	371	Markham, E. R.: Tool Making—17, 80, 190, 252, 301	
Intermittent Heating, Value of Gas for	371	Knibbs Patent, Litigation over the	258	Lindsay, D.: Boring Bar for Chasing Threads	153	Mathieu, J.: A Simple Indicator	277
Internal Combustion Engines and the Diesel Principle	39	Krupp Works, Essen and the Krupp Works, Wages in the	86	Radial Attachment for Boring Bar	330	Mat Surface on Steel, To Produce a. M. J. Oches	655
International Railway Congress Meeting	137	Kryptol, A New Substance for Electric Heating	141	Radial Slotting Attachment	268	Mayer, J.: Lathe Log for Heavy Cuts	552
Invention, A Lost (?)	184	Kwartz, E.: A Criticism	602	Lineshaft Clean, Keeping a. Robert A. Lachmann	442	May, John Mark: Advice to Apprentices	434
Invention in Great Britain, Germany and America	516	Labar, Alex. C.: To Coat Zinc Sheet Black for Tinsmith Work	331	Link Grinding Machine	313	McAnic: Should Machines be Bolted Down?	324
Iron and Its Early Manufacture in England. A. R. Bell	185	Labor-Saving Scheme for Making Drawings. C. W. Putnam	150	Link Motion for Rotating a Shaft—180 Degrees	214	Wonderful Taps and Dies	150
Iron and Steel from Corrosion, A New Process for the Protection of	142	Lachmann, Robert A.: Keeping a Lineshaft Clean	442	Litigation Over the Knibbs Patent	258	Something on the Heat Question as Affecting the Accuracy of Machine Operations	549
Iron and Steel Institute, Notice of Annual Meeting	390	Some Points About Oiling. Tools for Facing Work in the Lathe	160	"Little Drummer" Record Cards	584	Meade, Norman G.: Electric Repairing—187, 249, 307	
Iron, Effect of Ammonia on (How and Why 34)	390	Seen in a Jobbing Shop	552	Lloyd's, The Beginning of Loading, Eccentric. Frank B. Kleinhaus	30	Repairing Field Coils	529
Iron or Brass for Laying Out Work, To Prepare. Oliver E. Voris	444	To File a Sharp Scriber	597	Load on a Jib Crane. Dyer Smith	568	Measure the Radii of Deep-hole Drills, To. Otto Eckelt	298
Iron that Gave Us Leadership, The	23	A Pointer on Filing	604	Loabnitz Rock Cutter	148	Measuring Instruments, Some Micrometer. A. L. Monrad	41
Isometric Drawing, Triangle for. R. Grimshaw	386	Hack Saw Kinks	604	Locating and Aligning Shafting and Machinery, A Handy Tool for. Wm. H. Brooks	76	Mechanical Courses at Y. M. C. A.	137
Isometric Perspective, Notes on	74	Lacing Belts	276	Locating Pounds and Knocks. Location of Decimal Point in Slide Rule Calculations (How and Why 56)	319	Mechanical Engineering, Shop Training for. H. P. Fairfield	517
Jackson, F. H.: To Make Black Marks on Graduated Surfaces	655	Lamp, A New Incandescent. Lamp Suspension without Loose Wires, Portable	496	Lock, Hydraulic Lift	16	Mechanical Movement, An Ingenious. R. E. Flanders	489
Blackening Brass	444	Landis, Ezra F.: Carborundum Wheels	102	Locomotive Boiler Test Pump. A. E. Mitchell	442	Mechanical Movement, A Novel	634
Blackening Brass Work	495	Lard Oil on Machinery, Don't Use. C. F. Emerson	653	Locomotive First Transcontinental	85	Mechanical Science, Some Refinements of	243
To Write Black on Glass or Bright Metal	444	Lathe, A Large Bardons & Oliver	13	Locomotives as Fog Makers. Locomotives in Germany	36	Mechanical Toys, Badly Made	257
To Remove Bluing from Tempered Steel	605	Lathe Attachment for Turning Trolley Wheels. J. R. Gordon	47	London Underground System, Note on the	366	Mechanisms, Variable Speed. I.	458
The Use of Brass Wire in Brazing	605	Lathe, Bullard 36-inch Vertical Turret	367	Longest Pipe Line	160	II.	508
"Jaymac": Appliances for Boring, Facing and Turning Small Spur Gears	650	Lathe Job, An Uncommon. Straightedge	596	Loose Pulley Design for High Speed. James A. Pratt	435	III.	561
An Electrical Repair Job	652	Lathe Lead Screw, Length of Thread of (How and Why 31)	331	Loose Pulleys, Bristol	490	IV.	616
Jenkins, J. J.: High-Speed Steel in the Machine Shop of To-day	46	Lathe of the Turret Class, Improved	354	Lord, J.: Making T-Slot Cutters	323	Medal, A Leather. Carroll Ashley	150
Jib Crane and Traveling Jib Drill, Traveling	625	Lathe Rig for Turning Machine Handles, Draftsman	217	Lost, An Engine	85	Medal, The John-Fritz	477
Jib Crane, Load on a. Dyer Smith	568	Lathe Rollers for Finishing Work (How and Why 13)	161	Loetz, F. P.: The Designing and Making of Belts	295	Melville, David: Cement for Iron Rust Joint	605
Jig Blocks	433	Lathe, Some English. James Vose	21	Lubricant for Drawing Dies. J. M. Stabel	605	Mertes, A.: Something More Regarding Idle Machines	95
Jig for Drilling Angle and Strap Iron. H. J. Bachmann	488	Lathe, The "Lefries" Precision. Dr. Alfred Gradenwitz	147	Lubricants, A Novel Process for Testing. Dr. Alfred Gradenwitz	415	A Taper Roughening Reamer	95
Jig for Spacing and Drilling Holes at a Given Angle. Julius Lenhart	215	Lathe Tool, Radius. F. H. Whipple	437	Lubricating Oil from Pine Stumps	201	Time-saving Chucks	95
Jig Maker: Accurate Jig Making	270	Lathe Carriage for Screw Cutting, German. Robert Grimshaw	79	Lubricating Soap for Wire Drawing, Screw Cutting and Working Metals. A. F. Bierbach	444	Metals, Cement for. H. S. Gladfelter	655
Jig Making, Accurate. Frank Shailor	51	Lathe Dog for Heavy Cuts. J. Mayer	552	Lubrication, Improved	310	Metals, The Steel-Hardening. Jos. Hyde Pratt	473
Jig Making, Accurate. J. R. Gordon	156	Lathe Dog, Safety	496	Lubrication, Necessity of	200	Method of Securing Trade of Naxos Union Makers of Emery Wheels	637
Jig Making, Accurate. Jig Maker	270	Lathe Features, Some. Frank B. Kleinhaus	101	Lubrication of Springs; Is it Desirable?	370	Metric Leadscrew, Cutting English Threads with. A. L. Valentine	440
Jig Making, Accurate. J. R. Gordon	328	Lathe for Turning Cranks. G. L. F.	141	Lubrication System, Forced Grease	482	Meyers, L.: Etching Solution	444
Jig Milling and Drilling. H. J. Bachmann	595	Lathe for Turning Ellipses	372	Lucas, J. L.: Cold Chilling Process for Use on Finished Work in Iron, Brass or Steel	655	Michel, A. Eugene: Roller Chain Power Transmission and Construction of Sprockets	287
Jigs and Fixtures, How Defined	310	Lathe Gearing Compensation for Change of Lead due to Hardening. Hans Dahlstrand	436	Lutes and Cements, Notes on	296	Micrometer Beam Caliper, Improved	648
Jigs and Milling Fixtures with Operation Sheet. B. P. Fortin	265	Lathe Gearing for Quick Pitches. J. T.	380	Machine for Testing the Lubricating Qualities of Oils	524	Micrometer Depth Gage, An Addition to the B. & S. C. W. Shelly	654
Jigs and Tools for Machining Small Pistons. William N. Taylor	157	Lathe Tail Spindles, Boring Taper Holes in. E. H. Fish	651	Machine Handles, Lathe Rig for Turning. Draftsman	217	Micrometer for Test Bars, Foundry	371
Jigs, Bushing for Drilling and Reaming. O. C. Bornholt	491	Lathe with Quick Change Gear Device. Le Blond	22	Machine Operation, Phenomena of	536	Micrometer Gage for Milling Cutters. Robt. Grimshaw	443
Jigs for Shafts, Simple Drilling. Herman Jonson	221	Launching of the Connecticut	137	Machinery, Don't Use Lard Oil on. C. F. Emerson	653	Micrometer Gage, Six-inch. L. Norden	548
Jigs, Getting the Full Value Out of. J. F. Mirrieles	299	Launching of the New Jersey	208	Machinery from Rusting, To Keep. James A. Pratt	495	Micrometer Measuring Instruments, Some. A. L. Monrad	41
Jigs, Regarding Accuracy of. H. J. Bachmann	330	Laying Out Cone Pulleys, Graphical Method of. John Swanberg	552	Machinery, Large Special	257	Middlemen in Japan	201
John Fritz Medal, The	477	Laying Out Crown Brasses, Tool for. R. G. D.	219	Machinery, The Transition Period in	208	Mill, Adjustable, Hollow. V. H. Marcellus	51
Joint on Rough Surfaces by the Aid of Soft Metal, Making a. C. E. Mink	493	Laying Out Right-Angle Channel on End of Steel Block (How and Why 55)	606	Machining a 10-foot Gear. Geo. Renneisen	322	Miller, George: Gas Engine Economy	305
Jonson, Herman: Cutting off Stock in Engine Lathes	221	Laying Out Work, To Prepare Iron or Brass for. Oliver E. Voris	444	Machining, Small Pistons, Dies and Tools for	157	Milling a Large Screw. H. A. Houghton	384
Simple Drilling Jigs for Shafts	221	Lay-out of Pitch Circles of Elliptic Gears. C. E. Joseph	598	Machinist's Protractor	482	Milling and Drilling Jig. H. J. Bachmann	595
Non-Corrosive Soldering Fluid	495	Leak in a Tank, A Novel	257	Magnetic Alloys Made from Nonmagnetic Metals	423	Milling Attachment, Link	647
Winding Springs	221	Leather Belts, Glue for. L. E. Muncey	495	Magnetic Clutch Shifter. Herbert S. Gladfelter	271	Milling Cutters, Micrometer Gage for. Robt. Grimshaw	443
Polish for Brass. Polish for Steel	605	Leather can be Crimped. How (Answer to How and Why 42)	552	Magnets for Handling Iron and Steel, Lifting	363	Milling Cutters, The Shaping, Grinding and Hardening of	265
Transmission Rope Dressing	605	Leather Medal, A. Carroll Ashley	150	Maine, Raising the	258	Milling Cutters with Teeth Cast in. W. L. Fay	653
Construction of an Old Coffee Mill	653	Le Blond Lathe with Quick Change Gear Device	22	Making Oxygen from Liquid Air	585	Milling Flat Forming Cutters. W. E. Gould	602
Josselyn, C. E.: Layout of Pitch Circles of Elliptic Gears	598	Lectures at the Brooklyn Polytechnic, Evening	320	Manganese Rails for Sharp Curves	423	Milling Floor Grinder Bases. J. C. Spence	321
Journal Air Lubricated	52	Leire, George J.: Calculations for the Shaft, Gear and Bearings of Crane Motors	565	Manganese Steel, Notes on	359	Milling Machine Attachment for Threading Worm Wheels, Philadelphia	160
Keyseating Bar for Shaper Use. J. T.	277	Length of Thread of a Lathe Lead Screw (How and Why 31)	331	Manierre, J. E.: To True Universal Chuck Jaws	214	Milling Machine, Improved Vertical. Charles E. Burns	323
Keyseating, Planer Attachment. C. P. L.	327	Lenhart, Julius: Jig for Spacing and Drilling Holes at a Given Angle	215	Marn, W. I.: Dimensions of Ells and Tees for Wrought Iron Pipe	529	Milling Square Jaw Clutch Teeth. Draftsman	221
King, Patrick J.: A Neat Screw Driver	220	Leonard, W. S.: To Waterproof Glued Joints	495	Man Who is the Whole Thing, The. C. M. C.	100	Milling Square Thread Screws	648
Notes on the Strength of Beams, Plates, and Columns	526	Lettering Drawings, A Device for	8	"Man Who is the Whole Thing, The." Foreman	321	Milling the Under Side of Bolt Heads, Rig for. W. C. F.	494
Kingsley, E. R.: Wire Straightener	220	Leveling Machine Tools, The Importance of. Sellem	97	Marcellus, V. H.: To Harden Thin Saws Without Warping	491	Mining Cages Have Safety Catches? Why do Not	85
Kleinhaus, Frank B.: Eccentric Loading	30	Levin, A. M.: Modern Steam Hoisting Machinery	453	Adjustable Hollow Mill	51	Mink, C. E.: Cement for Holes and Cracks in Castings	605
Bending Angles and Structural Shapes	306			Spring Strippers Construction	272	Solution for Drilling Hard Steel	495
Correction of a Calculation in "Eccentric Loading"	354			Blanking and Forming Dies	649		
				Marine Craft in America, Slow Construction of	139		

Making a Joint on Rough Surfaces by the Aid of Soft Metal	493	Oil Grooves and the Fitting up of Bearings. C. H. Bierbaum	459	Planer Drive, New Cushion. 371	Pulleys, The Bursting Strength of Wooden. C. H. Benjamin	613
Sulphur as a Packing Between Bed Plates and Foundations	435	Oil in Boiler Furnaces, Danger of	533	Planer with Air-operated Friction Clutches, Ninety-six Inch Sellers.	Pulverizing Borax, Process for. Albert D. Knavel	444
Covering Pulleys with Leather	596	Oiling, Some Points About. Robert A. Lachmann	442	Planing a Cross Groove. Eugene Wopaletsky	Pumping Engine, A. Worthington	90
Mixture for Fire Cement. Minnesota, The	605	Oil Grooves and the Fitting up of Bearings. C. H. Bierbaum	442	Planing Engine Beds. F. H. J.	Pumping Heavy Fluids.	406
Mirrieles, J. F.: Getting the Full Value Out of Jigs	299	Oily Steel, Copper Solution that will Color on	655	Planing Keyways in Shafts, V-blocks for	Pumping Machinery, The Limit in	402
Mitchell, A. E.: Compressed Air as an Aid to Fan Blast in Forge Shop	437	Old Tools, Motor Drives for. One-Turn Clutch. John D. Adams	406	Planing Spiral Corrugated Rolls. W. L. Fay	Pumps, The Action of	636
Locomotive Boiler Test Pump	442	Oscillating Engine, Counterbalancing an	598	Planing Thread Tools, Formula for. A. L. Valentine	Punch and Die, Adjustable, to Cut Sectors of Various Lengths. H. J. Bachmann	34
Handy Water Connection for Car Wheel Press.	443	Otis, Robert B.: Using a Hacksaw as a Parting Tool in the Lathe	632	Plans for the Carnegie Engineering Building	Punch and Die for Making Number Plates. W. Van Orman	387
Modern Steam Hoisting Machinery. A. M. Levin	453	Oto, F. H.: To Blacken Brass for Templet Work and Other Purposes	161	Plate Planers, Double-Head Tool for. Toolmaker	Punch and Die for Making Square Nuts. O. E. Perrigo	50
Modern Work with Ancient Tools. E. J. Buchet	649	Our Record of New Tools.	495	Plenum Heating System and Coke Air Washing Apparatus of B. F. Sturtevant Co.	Punch and Die for Steel Range Work, Compound. W. Van Orman	492
Molder, Making a	639	Output of a Machine, A Small Change that Made a Big Improvement in	422	Plotting Curve from an Inaccessible Center, Method of Plug Gage Construction, Improved. W. E. G.	Punching Die for Making Labels. Paul R. Werner	271
Monrad, A. L.: Some Micrometer Measuring Instruments	41	Pacific Steamships Minnesota and Dakota	389	Plugging Holes in Cast Iron, Mixture for. R. B. Casey	Punching Small Holes in Tool Steel Blanks. Joseph V. Woodworth	470
Muffle Brazing	103	Page, Julian D.: Checking a Drawing	55	Pneumatic Tube System, Proposed Long-distance	Putnam, C. W.: Labor-saving Scheme for Making Drawings	269
Monument to Eli Whitney. Mortar for Stopping Holes in Boiler Settings, etc. F. Emerson	84	Making a Core Box from the Pattern	382	Pointer on Filing. A. R. A. Lachmann	Quenching Baths for Tempering Cutting Tools, Composition of	419
Motor Drive as Applied to Cotton Mills	655	Panama Canal Problem, The Panama Canal, The	585	Polish for Brass—Polish for Steel. Herman Jonson	Questions, The Doubtful Joy of Answering	49
Motor-driven Fire Engines in Vienna	533	Panama Canal, Regulations for Employees at	158	Porous Casting Air- and Water-tight, Mixture for Making a. L. S. Burbank	Quick Action Bench-Vise	478
Motors and Dynamos, Small. E. E. Warner	438	Paradox, The Telephone	245	Portable Home-made Planer, A Portable Lamp Suspension without Loose Wires	Quick Change Gear Device, Le Blond Lathe with	422
Motors on Fishing Boats	84	Parallel Motion for Drawing Board. H. M. B.	405	Portland Cement, Effect of Oil on	Quick Job, A	83
Motors to Machine Tools, Application of	372	Parting Tool in the Lathe, Using a Hacksaw as a. Robt. B. Otis	422	Portland Cement When Mixed With Water, Properties of Port Richmond Iron Works, Heavy Work of the	Quick-return Shaper Motion. E. H. Fish	22
Motor Drives for Old Tools. Motors, Gasoline	406	Patent Issued in 1828, Copy of a	33	Post-box on the Principle of Coin-in-the-slot Machine	Quick Pitches, Lathe Gearing for	130
Motors, Variable Speed. Wm. Baxter	85	Patent Laws, Proposed Revision of the	215	Power Hoist, Weight Needed on Lever of a (H. & W. 26)	Quivering in Machine Tools, To Prevent	97
Mottle Casehardened Pieces, To. Harry Ash	513	Patent Law, A Strange	222	Power in Street Railway Service, Cost of	Radial Attachment for Boring Bar. E. Lindsay	380
Mottling Casehardened Work Muffle Brazing. A. L. Monrad	144	Patent Laws, Stricter British Patents. Some Facts Concerning	404	Power Plant of the Hotel Astor	Radial Slotting Attachment. D. Lindsay	278
Multiple Threads with a Chaser, Cutting. T. E. Remington	103	Patterns for Chuck Plates. E. H. Fish	416	Power Plants, Vertical Boilers in	Radii of Deep-hole Drills, To Measure the. Otto Eckelt	317
Multi-Stage Centrifugal Pumps for Elevator Service	330	Pattern Shop of the U. S. Naval Gun Factory. Edwin M. Birrell	51	Power-transmission by Frictional Gearing (H. & W. 21)	Radium and Energy	199
Muney, L. E.: Chuck for Holding End Mills	583	Peary's New Arctic Ship, Machinery and Hull of	241	Practical—Dies for Making Tin Nozzles	Radium, New Theories Concerning	277
Chuck for Holding End Mills	105	Peat Gas as a Source of Power Peat, Recuperative Power of Pennies doing the Work of Dimes	477	Practical Don'ts for Machinists. H. E. Wood	Radius Lathe Tool. F. H. Whipple	487
Glue for Leather Belts.	495	Pennsylvania Tunnel, Progress on the	141	Practical Inspector, The. E. N. Percy	Railway, First American Alternating Current	530
For Bluing Small Brass and Steel Articles by Immersion	605	Percy, E. N.: The Practical Inspector	85	Pratt, James A.: Estimating Cost, with Examples Illustrating Application of Method	Railway Trains, Resistance of. G. L. F.	69
Myers, John S.: Beams and Planes with Several Supports, A Criticism	30	Petroleum Briquetting	403	Preparing Iron or Brass for Laying Out Work. Oliver E. Voris	Raising the Maine	487
On the Strength of Timbers	322	Philadelphia—Fixture for Boring Brasses	495	Press, A. P.: How Bill Changed His Job A Vacation and What Came of It	Ramp, J. B. (Obituary)	444
Charts in Designing—9, 90, 145	145	Photographing Shop Interiors	443	Pressure of Modern Guns, Enormous	Rams of Boring Mills, Balancing Arrangement for the	35
Myers, L.: Tool for Boring Rotary Pump Casing	440	Photographs of Steam Turbine Blades, Interesting	495	Press with Special Feed, Bliss Preventing Vibration in Steamships, Method of	Rautenstrauch, Walter: Notes on Riveted Joints	258
Name Plates, Concerning	612	Photography, Value of	495	Prick Punch Holder. M. H. Ball	Raymond, Prof. W. G.: Increase in Engineering Courses	144
National Machine Tool Builders' Association	471	Piecework Shops, A Problem for the	443	Prick Punch with Adjustable, Automatic. Otis L. Storer	Razors, High Speed Steel	202
National Machine Tool Builders' Convention	181	Pile Drivers, Superiority of Drop Hammer for	443	Prick Punch with Interchangeable Scriber Points. C. C. Arras	Real Efficiency of Steam Boilers, The	423
National Machine Tool Builders' Convention, Next Year Method of Keeping Screws	331	Pillow-block Seat of a Large Engine was Planed out with a Small Planer, How the. E. J. Buchet	443	Prime Movers, Comparisons and Notes on	Reamer, A Taper Roughening. A. Mertes	256
Neil, C.: A Turret Parting Tool	441	Pins Used in Chord System of new Blackwell's Island Bridge, N. Y.	443	Preparing Iron or Brass for Laying Out Work. Oliver E. Voris	Reamer Extensions, Two	587
New Anti-Friction Metal, The	500	Pipe Center. Francis W. Shaw	443	Press, A. P.: How Bill Changed His Job A Vacation and What Came of It	Reamer, Using a Tap as a. R. B. Otis	95
New President for Lehigh University	612	Pipe Centers. J. T.	443	Pressure of Modern Guns, Enormous	Receiving Mechanism, Delicate	220
New Tools of the Month	56	Pipe Fishing Job. A. Otis D. Storer	443	Press with Special Feed, Bliss Preventing Vibration in Steamships, Method of	Reciprocating Parts in Engines, Result of Reducing	161
(2)	108	Pipe Flanges, Standard Hydraulic. F. B. Kleinbans	443	Prick Punch Holder. M. H. Ball	Recording Angular Velocities of Marine Shafting	119
(3)	162	Pipe Joints for High-Pressure	443	Prick Punch with Adjustable, Automatic. Otis L. Storer	Record of New Tools, Our	139
(4)	223	Piston Rings, Making. Steel Piston Rings, Rig for Re-turning. Stanley Gould	443	Prick Punch with Interchangeable Scriber Points. C. C. Arras	Recut Old Files, To. R. B. Casey	590
(5)	279	Pitch for Road-making	443	Prime Movers, Comparisons and Notes on	Reducing Sleeve for Pump Cylinders	422
(6)	332	Planer and Lathe Cutter and Boring Bar. A. B. C.	443	Problem for the Piecework Shops, A	Refrigerating Plant for Every House, A	141
(7)	392	Planer, A Portable Home-made	443	Producer Gas Engines on Shipboard	Reinforced Concrete	588
(8)	446	Planer Bar with Stiff Support. F. Emerson	443	Production of Light, Energy Expended in	Reinforced Concrete Piles	368
(9)	499	Plancher, A Portable Home-made	443	Projection, Anisometric. Robert Grimshaw	Relative Cost of Cutting by Emery Wheels and by Filing	141
(10)	554	Planer Drive, New Cushion. 371	443	Properties of Portland Cement When Mixed with Water	Relieving the Teeth of Hand Taps. (H. & W. 54)	606
(11)	608	Planers, High Speed. A. L. De Leeuw	443	Proportions and Character of Sand and Gravel to Use in Concrete	Remedy for Injured Steel	88
(12)	658	Planer with Air-operated Friction Clutches, Ninety-six Inch Sellers.	443	Proportions of Twist Drills. H. D.	Remington, T. E.: Cutting Multiple Threads with a Chaser	330
New York Subways, Proposed at	312	Planing a Cross Groove. Eugene Wopaletsky	443	Proportions for a Cast-Iron Spring Piston Ring (H. & W. 38)	Reminiscences, Some Personal. Joseph H. Springer, Sr.	551
Niagara Falls, Power Station	423	Planing Keyways in Shafts, V-blocks for	443	Proposed Revision of the Patent Laws	Rennelsen, Geo.: Machining a 10-foot Gear	322
Niagara Power Houses, Sizes of the Three New	423	Planing Spiral Corrugated Rolls. W. L. Fay	443	Protection of Iron and Steel from Corrosion, A New Process for the	Repairing a 400-Ton Hydraulic Press. Frank M. Davis	630
Niagara Water Power	534	Planing Thread Tools, Formula for. A. L. Valentine	443	Protective Devices in Shops. Protractor, Machinists'	Repairing Commutators in which the Mica Insulation has Burned Away	645
Nickel for Coinage, Use of Pure	637	Plans for the Carnegie Engineering Building	443	Pulley Crowning Device. Theo. Disch	Repairing Electric. Norman G. Meade	187
Nickel Steel, Use and Value of Niemand, I. B.: Test Gage for Maintaining Standard Tapers	220	Plate Planers, Double-Head Tool for. Toolmaker	443	Pulleys, Loose. Bristol	(1) The Commutator	249
Non-Corrosive Soldering Fluid. Herman Jonson	495	Plenum Heating System and Coke Air Washing Apparatus of B. F. Sturtevant Co.	443	Quenching Baths for Tempering Cutting Tools, Composition of	(2) Armature Winding	307
Norden, L.: Six-Inch Micrometer Gage	548	Plotting Curve from an Inaccessible Center, Method of Plug Gage Construction, Improved. W. E. G.	443	Questions, The Doubtful Joy of Answering	(3) Armature Coils	529
Not as Rich as We Seem	24	Plugging Holes in Cast Iron, Mixture for. R. B. Casey	443	Quick Action Bench-Vise	Repairing Field Coils. Norman G. Meade	652
Number Plates, Punch and Die for Making. W. Van Orman	50	Pneumatic Tube System, Proposed Long-distance	443	Quick Change Gear Device, Le Blond Lathe with	Repair Job, An Electrical "Jaymac"	636
Nut Locks	86	Pointer on Filing. A. R. A. Lachmann	443	Quick Job, A	Repair Jobs, Emergency	478
Oches, Max J.: To produce a Mat Surface on Steel	655	Polish for Brass—Polish for Steel. Herman Jonson	443	Quick-return Shaper Motion. E. H. Fish		
Office Building, A New Sturtevant	390	Porous Casting Air- and Water-tight, Mixture for Making a. L. S. Burbank	443	Quick Pitches, Lathe Gearing for		
Oil Filter, German	648	Portable Home-made Planer, A Portable Lamp Suspension without Loose Wires	443	Quivering in Machine Tools, To Prevent		

Re. Pedro: Striking up Forming Dies.	384	Setting for Turning Tapers. J. T.	52	Spring Dies Closing In. To Prevent. W. Van Orman.	105	Steel-tired Wheels, Advan- tages of	477
A Tapping Experience.	276	Sewing Machine which Sews Direct from Two Spools of Thread	637	Spring Latch, Making a. H. R. H.	152	Stegeman, Oscar: Direc- tions for Drawing Iz. C. Coils.	174
Repetition Castings, Gang Milling of, J. V. Wood- worth	582	Shaft Coupling of The Re- public Engineering Co.	644	Spring Strippers Construc- tion. V. H. Marcellus.	272	Still Safe, The Connecticut. Storage Battery, New Type of Storer, Otis D.:	138 533
Reply to "A Criticism." O. E. Perrigo	602	Shafts, Connecting (H. & W. S.)	107	Spur Gears, Angle of Pres- sure of	331	Automatic Prick Punch with Adjustment	381
Report on Black Powder by Chief Mason of Bureau of Ordnance	472	Shallor, Frank E.: Notes on Toolmaking	210	Boring, Facing and Turn- ing Small. Jaymac.	650	Device for Turning Steam Roll Necks	438
Research, Steam Engine	483	Accurate Jig Making	51	"Spur Gear Teeth, Giving Diametral Pitch, Table of"	383	A Pine Fishing Job.	604
Resistance of Emery Wheels to Rupture, The.	35	Re-cutting Thread Chasers Gage Making	546	"Spur Gear Teeth, Giving Diametral Pitch, Table of, Error Corrected in.	276	"Straightedge"—An Uncom- mon Lathe Job.	596
Resistance of Jacketed Bul- lets when Forced through the Bore of 0.30 Caliber Rifle Barrels	635	Shape of Rolls for Cylinder Cams, On the. R. E. Flanders	209	Spur Gear Teeth, Giving Diametral Pitch, Table of, L. S. Burbank.	212	Straighten Bruised Threads, To	389
Resistance of Railway Trains. G. L. F.	35	Shaper Tools, Device for Pre- venting Wear of. A. R. Chern	98	Spirally Corrugated Boiler Tube, A	86	Street Car Used in Cincinnati Strength of Beams, Plates and Columns, Notes on the. R. P. King	639 526
Result of Reducing the Weight of Reciprocating Parts in Engines.	139	Shaping, Grinding and Hard- ening of Milling Cutters, The	205	Springer, Sr., Joseph H.: Some Personal Reminiscen- ces	551	Strength of Beams with Ribbed Sections—A Para- dox	176
Retirement of George A. Gray of Cincinnati, Ohio.	476	Sharp Curves, Manganese Rails for	423	Square Nuts, Punch and Die for Making. O. E. Perrigo Square Thread Screws, Mill- ing	492 648	Strength of Columns, The.	428
Re-turning Piston Rings, Rig for. Stanley Gould.	488	Shaw, C. J.: Graduating for De- grees in the Index Head.	442	Square Thread Taps in Sets. Stabel, J. M.:	379	Strength of Timbers, On the. John S. Myers.	322
Rewinding of Armature.	486	Shaw, Francis W.: Pipe Center Shear Steel, Method of Mak- ing	232	Lubricant for Drawing Dies	605	Strength of Timber Treated with Cresote or Zinc Chloride, The	477
Ridge Machine Tool Co., New Plant of the	407	Shaw, C. J.: To Reduce Small Drill Breakage	494	To Prepare Emery for Fine Lapping	494	Strength of Tobin Brass Al- loys	520
Rifle Gun, Ball-bearing.	32	Hot Water for the Tin Shop	277	Paste for Hardening High- Speed Steel	495	Striking up Forming Dies. Pedro Re	384
Rifle Sight, A New.	85	Shelly, C. W.: Making Drop For- ging Dies	266	An Expansion Chuck.	549	Sturtevant Economizer	106
Riley, Joseph C.: A Process for Copying Printed Pictures	5	An Addition to the B. & S. Micrometer Depth Gage	654	Tables Giving Angles of Threading Tools	599	Sturtevant Office Building, A New	300
Riveted Joints, Notes on.	401	Sherardizing Process for Gal- vanizing Iron, New.	637	Varnish for Steel.	605	Sturtevant Co., B. F.: Plenum Heating System and Coke Air Washing Appar- atus of the	529
Roll-Making, Pitch for.	139	Shop Arrangement and Cost of Output	138	To Blacken Brasswork for Instruments	655	Subterranean Fires	70
Rolled Steel Car Wheels.	427	Shop Cost Troubles, More. Iayonac	414	"Standard" Nose Threads for Lathe Spindles, James Ar- thur	95	Subway Employees	53
Roller Chain Power Trans- mission and Construction of Sprockets. A. Eugene Michel	287	Shop Interiors, Photograph- ing	84	Standard Precision Screw.	424	Subway Notes Worth Preserv- ing	182
Rolling Process, To Make Gear Wheels by a.	497	Shop Training for Mechanical Engineering, Howard P. Fairfield	517	Standard Tapers Test Gage for Maintaining. I. B. Niemand	220	Subways, Proposed New York Successful Apprentice, A.	99
Rolls for Cylinder Cams, On the Shape of. R. E. Flan- ders	209	Shopwork Instruction	532	Starting and Regulating Rheostats for Machine Tool Drives	500	Suction Gas Producer, De- sign and Operation of.	535
Ropes in Mines	12	Should Machines be Bolted Down? McAnic	324	Statistics of the World's Out- put of Coal.	467	Sulphur as a Packing Be- tween Red Plates and Foundations, C. E. Mink. Sulphur Deposits at Calcasieu Parish, La., Working of	435 477
Rosenthal, L. S.: Turret Tool Holder.	159	Shrinkage Allowance in Drop- Forging Dies for Copper. (H. & W. 43)	498	Statistics, Rubber Industry. Staybolts, Braces and Flat Surfaces	418 263	Summer School for Artisans, 5th Annual Session.	415
Rotary Pump Casing, Tool for Boring. L. Myers.	440	Shrinking Nuts or Rings for Permanent Set. C. D.	159	Staybolts for Oil-burning Boilers, Radial	203	Superheated Steam for Loco- motives in Germany.	36
Rotating a Shaft 180 De- grees, Link Motion for. J. D. Adams	214	Signaling in Australia, New System of	140	Steam and Electric Traction Compared	90	Superheated Steam, Specific Heat of	521
Rotation of Marine Propeller Wheels, Direction of.	137	Silver Paste for Brass. J. S. Gordon	391	Steam Boilers, The Real Effi- ciency of	587	Surgery, Simple Eye.	119
Rough Castings, A System of Drill Jigs for. H. J. Bachmann	209	Simple Ball Reamer	104	Steam Engine Research.	483	Swanberg, John: Graphical Method of Lay- ing Out Cone Pulleys.	552
Rowe, C. H.: Regarding the Teeth of Hollow Mills	215	Simple Drilling Jigs for Shafts, Herman Jonson.	221	Steam in Nozzle of a Tur- bine. (H. & W. 7)	54	Sweet, Prof. John E.: The Apprenticeship Ques- tion	52
Rubber Industry Statistics.	418	Simplicity of Electric Fur- nace Processes	607	Steam Pipes and Boilers, In- sulating Covering for. Theodore Disch	444	System of Drill Jigs for Rough Castings, A. H. J. Bachmann	209
Rules for Calculating Speed Reduction and for Finding the Number of Teeth of the Gears that will give a Desired Ratio	445	Six-Inch Micrometer Gage. L. Norden	548	Steam Pipes, Permanent Iron Cement for, James H. Tay- lor	495	Table of Spur Gear Teeth Giving Diametral Pitch, L. S. Burbank	212
"Run of Stone," Value of a. (H. & W. 9)	107	Sketching Camera, A. War- ren E. Willis.	326	Steam Pipes, Water Hammer in	37	Table of Tangents, To Lay Out Angles from.	220
Rust Joint. D. Melville.	655	Slide Rule, The—Position of the Decimal Point. S. E. Woodbury	189	Steam Roll Necks, Device for Turning. Otis D. Storer.	438	Tables Giving Angles of Threading Tools. Jos. M. Stabel	599
Rust Joint Mixture.	33	Sliding Keyways, Friction of. James Arthur	218	Steam Turbine be Started in an Emergency Quicker than a Reciprocating Engine of the Same Power? Can a.	592	Tables Showing the Succes- sive Events in Three- and Four-Cylinder Gas Engines. R. L. Williams	435
Safety Catches? Why do not Mining Cages have.	85	Sliding Keyways, Friction of. Slotted as a Machine Tool. The	476	Steam Turbine Blades, Inter- esting Photograph of.	471	Tap as a Reamer, Using a. Robert B. Otis.	161
Safety Device for Setscrews. Simple. Warren E. Willis	442	Slow Construction of Marine Craft in America.	139	Steam Turbines, Condensers for	260	Tantalum	520
Safety Lathe Dog.	496	Small Drill Breakage, To Re- duce. P. B. Shee.	494	Steam Turbine Construction, The Trend in.	24	Taper Roughing Reamer, A. A. Mertes	95
Salt-water and Boiler Scale. Sand Blast Apparatus for Cleaning Tenders	184 89	Smallest Electric Motor Made Small Motors as Generators. (H. & W. 46)	139 498	Steam Turbine, The Hamil- ton Holzworth	134	Tapers, Setting for Turning. J. T.	52
Saws without Warping, To Harden Thin. V. H. Mar- cellus	494	Smith, Dyer: Load on a Jib Crane.	568	Steam Turbine, The Lind- mark	304	Tapping Experience, A. Pe- dro Re	276
Scientific and Engineering Supplement to be Published with London "Times," Weekly	390	Smoke and its Abatement.	590	Steam Turbine Patents. A Review of— (1) (2) (3) (4)	1 115 237 291	Taps and Dies, Wonderful. McAnic	150
Seranton Meeting of the A. S. M. E.	593	Solder and its Abatement.	605	Steel: Making Piston Rings.	155	Taps in Sets, Acme.	268
Screw Cutting, German Lathe Carriage for. Robert Grim- shaw	79	Softening Hard Cast Iron for Drilling, To. O. E. Voris Solder for Brass and Steel, Non-rusting. (H. & W. 4)	494 545	Steel Brazing, Hard Solders for	311	Taps in Sets, Square Thread. H. D.	379
Screw Cutting Kink, Eugene Wopaletsky	159	Soldering Acid and Solders, A. Soldering Aluminum. R. E. Weinland	494 627	Steel Cage Building Construc- tion	640	Tariff on Machine Tools, Ger- man Manufacturers De- mand	139
Screw Cutting with the Feed Gear. J. T.	104	Soldering Aluminum Patterns Soldering Copper Conductors, Notes on. G. L. F.	478	Steel Can be Cut Faster than Cast Iron, Why.	625	Taylor, Charles G.: Three-piece Ellipsograph: A Criticism Taylor, J. H.: Permanent Iron Cement for Steam Pipes.	386 495
Screw Driver, A Neat. Pat- rick J. King.	220	Soldering Fluid, Non-Corro- sive. H. Jonson	495	Steel, Coloring. Harry Ash. Steel-concrete Construction.	391 86	Taylor, Wm. N.: Jigs and Tools for Machining Small Pistons.	157
Screw Machine, Self-aligning Holder for	388	Soldering Fluid, Non-Rusting. F. E. Whittlesey.	444	Steel Forging and Tempering. Tool. R. H. Henderson.	67	Technical Education, Con- temporary	245
Screw Machines for Thread Cutting, Camming. G. H.	388	Solders for Steel Brazing, Hard	311	Steel Gears, Speed and Ma- terial for. (H. & W. 20)	222	Technical Publicity Associa- tion	542
Screw Thread, Callipering the Fit of a. H. E. Wood.	275	Solution for Beams, Graphi- cal	214	Steel Hardening and Temper- ing Compound, H. S. Hind- man	444	Technology Club of Syracuse, N. Y.	85
Sears, W. T.: To Harden Cast Iron.	444	Solution of Question No. 55, Simple. A. L. DeLeeuw.	656	Steel, High-Speed	85	Teeth Cast in Milling Cutters with. W. L. Fay.	6
To Keep Water from Freez- ing or Souring.	444	Solution of the Bevel Curve. Charles Clonkey	93	Steel, Increased Consumption of	477	Teeth in Gears as Used in Rolling Mills, the Forms and Relative Advantages of	485
Hydraulic Valve Improve- ment	270	Something About This De- partment	605	Steel Mills, Electric Motors in	544	Teeth of Hollow Mills, Re- garding the. C. H. Rowe.	215
Sectional Fixture, A. Ralph E. Flanders	93	Special Counterbore. W. C. Force	652	Steel Production Per Annum Steel Range Work, Compound Punch and Die for. W. Van Orman	33 271	Telephone Paradox, The.	33
Securing Inserted Blades, Method of	425	Specific Heat of Superheated Steam	521	Steel Scale—Handy Screw- driver	619	Temper Cold Chisels, To. (H. & W. J. F. D.)	553
Seen in a Jobbing Shop. R. A. Lachmann	552	Speed and Material for Steel Gears. (H. & W. 20)	222	Steels Suitable for Various Tools	423	Tempering Circular Saws Used in Cutting Metals, Receipt for (H. & W. 47)	552
Segment Gears, Facing. H. G. Self-aligning Holder for Screw Machine. C. M. Dall.	221 388	Speed in Wood-working Ma- chinery	33	Steel, Thermal Conductivity of Low and High-Carbon. Steel Tracks for City Traffic, Failure of	201 201	Tempering Cutting Tools, Composition of Quenching Baths for	478
Seltem: The Importance of Lev- eling Machine Tools.	97	Spence, J. C.: Milling Floor Grinder Bases	321				
Sensitive Governing under High Heads	86	Spherical Boring and Turn- ing in the Allis-Chalmers Shops	574				
Septa and Blue-print Paper. (H. & W.)	54	Spiral Corrugated Rolls, Planing. W. L. Fay.	274				
Setscrews, Simple Safety De- vice for. Warren E. Willis	442	Sports, Indifference of Ger- man Workmen to	87				

Terminal Facilities, Inadequate	430	Transition Period in Machinery, The	208	Van Orman, W.: Combination Forming Die	438	Wattmeter Can be Made to Creep, How (H. & W. 53)	606
Test Gage for Maintaining Standard Tapers, I. B. Niemand	220	Transmission of Power by Frictional Gearing	222	Number Plate for Making Compound Plates	50	Wear of Shaper Tools, Device for preventing, A. R. Chern	98
Testing, Gas Engine	376	Transmission Rope Dressing, H. Jonson	605	Compound Punch and Die for Steel Range Work	271	Wear of Turbine Blades	619
Testing Krupp Guns in a Tunnel	637	Transportation in New York, Proposed Five Levels of	88	To Prevent Spring Dies Closing in	105	Webster, J. A.: Carriage Stop for Lathe	383
Testing Lubricants, A Novel Process for, Dr. Alfred Gradenwitz	415	Traveling Jib Crane and Traveling Jib Drill	625	Variable Speed Mechanisms—1	458	Estimating the Cost of Machine Work	560
Testing Lubricating Qualities of Oils, Machine for	524	Triangle for Isometric Drawing, Robert Grimshaw	386	(2) Cone Disk and Sphere Devices	508	Weight Needed on Lever of a Power Hoist (H. & W. 26)	278
Test Pump, Locomotive Boiler, A. E. Mitchell	442	Triple Vapor Engine	140	(3) Cone and Disk Devices	561	Weight of a Crowd of People	424
Tests of Helical Springs	624	Triple Worm was Cut, How a. R. B. Casey	220	(4) Expanding Pulleys	616	Weinland, R. Earl.: Soldering Aluminum	494
Tests on High Speed Steel	475	True Universal Chuck Jaws, To, J. E. Manierre	214	Variable Speed Motors, William Baxter, Jr.	584	An Advertising Scheme	547
The Minnesota	25	T-Slot Cutters, Making, J. Lord	323	Variable Speed Motors, William Baxter, Jr.	584	Welding, Gold	107
Theories Concerning Radium, New	424	Tube Cleaners, Destructive Action of Internal	315	(6) The C. & C. Electric Company's Series Parallel System	26	Welding Locomotive Frames, Thermit	645
The Possibilities of Bog Fuel The Progress of the Connecticut	200	Tunnel, Another Alpine	369	(7) Commercial Electric Co's System	120	Weller, R. M.: Facing Bar Holder	269
Thermal Conductivity of Low and High-Carbon Steel	201	Tunnel System of Chicago	637	(8) The Stow Multi-Speed Motors	171	Werner, Paul R.: Punching Die for Making Labels	269
Thermit Welding Locomotive Frames	645	Turbine and its Manufacture, De Laval Steam	123	(9) The Cutter-Hammer Variable Speed Controllers	246	Westinghouse Compound Air Pump	640
The Trend in Steam Turbine Construction	24	Turbine, An Experimental Gas, Dr. Alfred Gradenwitz	169	(10) The H. Ward Leonard and Controllers	348	What Is the Cause of this Trouble? W. K.	95
Thiel, Charles: Making Formed Cutters on the Lathe	216	Turbine Blades, Wear of	619	(11) The Thomson-Ryan Variable Speed Motor	399	Wheels, Rolled Steel Car	427
Thread Chasers, Recutting, Frank E. Shailor	104	Turbine Co., The De Laval	61	(12) The Electro-Dynamic Co's Inter-Pole Variable Speed Motor	513	Wheel, Steel-tired	477
Thread Drawn from Melted Quartz	264	Turbine Engine, First Large War Vessel to be Equipped With	460	Varnish for Cast Iron Patterns, J. A. Pratt	605	Whipple, F. H.: Radius Lathe Tool	437
Thread Gages, The Grinding of, J. R. Gordon	78	Turbines, Impulse and Reaction	346	Varnish for Steel, J. M. Stabel	605	Whitewash, Grant's Receipt for, W. E. G.	391
Threading Worm Wheels, Milling Machine Attachment for	160	Turbine, The Crucial Test of the	532	V-blocks for Planing Keyways in Shafts	433	Whitney, Monument to Eli	84
Threads on a Metric Lathe, Cutting, English System	330	Turning Cranks, Lathe for, G. L. F.	141	Ventilating Blower with Motor	55	Whittlesley, F. E.: Non-Rusting Soldering Fluid	444
Thread Tools, Formula for Planing, A. L. Valentine	489	Turning Shaft Longer than Center Distance of Lathe, C. H. A.	105	Ventilation, Amount of Air Required for	619	Williams, R. L.: Tables Showing the Successive Events in Three and Four Cylinder Gas Engines	435
Three and Four-Cylinder Gas Engines, Tables Showing the Successive Events in, R. L. Williams	435	Turning Steam Roll Necks, Device for, Otis D. Storer	438	Ventilator of the Albespeyre Tunnel, The, Dr. Alfred Gradenwitz	32	Willis, Warren E.: Simple Safety Device for Set-screws	442
Three M's, The	319	Turning Tapers, On, (H. & W. 12)	161	Vertical Boilers in Power Plants	199	A Sketching Camera	326
Three-piece Ellipsoidograph Again, John D. Adams	491	Turning Trolley Wheels, Lathe Attachment for, J. R. Gordon	47	Vertical Mill, An Expansion Chuck for the, Uncle Josh	380	Winding Springs, Herman Jonson	221
Timber Preserving Plant	199	Turret Lathe, Bullard 36-inch Vertical	367	Vertical Milling Machine, Improved, Charles E. Burns	323	Wireless Ship Localizer, De Forest	290
Timbers, On the Strength of, J. S. Myers	322	Turret Parting Tool, A. C. Neil	441	Vertical Milling Machine, Improved, Charles E. Burns	323	Wire Rope, Making	202
Timber, Treated with Creosote or Zinc Chloride, Strength of	477	Turret Tool Holder, L. S. Rosenthal	159	Vibration in Steamships, Method of Preventing	538	Wire Ropes, Bending Stresses in	426
Time-saving Chucks, A. Merz	95	Twist Drills, Proportions of, H. D.	646	Villars, J. D.: Formula for Differential Indexing	154	Wire Straightener, H. J. Bachmann	151
"Times" Building, The New	311	Typewriter, Adding Attachment for the	371	Voris, Oliver E.: To Prepare Iron or Brass for Laying out Work	444	Wire Straightener, E. B. Kingsley	220
"Times" New Engineering and Scientific Supplement, London	390	Typewriting Machine, Newly-invented German	585	To Soften Hard Cast Iron for Drilling	605	Woodbury, S. E.: The Slide Rule, Position of the Decimal Point	189
Tinning Wire Goods, Process for, (H. & W. 51)	606	Uncle Josh: An Expansion Chuck for the Vertical Mill	380	Vose, James: Some English Lathes	21	Wood, H. E.: Calipering the Fit of a Screw Thread	275
Tin Nozzle, Dies for Making, Practical	487	Under Cutting Tool, Feed Relief for Planer, H. D. Elliott	654	Wages in the Krupp Works	86	Practical Don'ts for Machinists	530
Tobin Brass Alloys, Strength of	520	Underground, The London	366	Walter Kimball, of Richmond, Va.	264	Wood Pavement in Hull, England	311
Tool-Carriers, Oscar E. Perrigo	575	"Unor"—a New High Speed Steel	638	Ward, Wilfred B., Richmond, Ind. Account of Grandfather's Old Shop	421	Wood Preservation	130
Toolmaker—Double-Head Tool for Plate Planers	443	Use and Value of Nickel Steel	290	Warner Auto-Meter, The	362	Wood-working Machinery, Speed in	33
Toolmaker's Files, by American Methods, The Making of Fine	431	Use of Electricity for Heavy Railway Operations	533	Warner, E. E.: Small Motors and Dynamos	438	Woodworth, Joseph V.: Punching Small Holes in Tool Steel Blanks	419
Toolmaking—E. R. Markham: (10) Arbors	17	Use of Forced Draft instead of Induced Draft	533	War-vessel, New British	638	A Novel Drill Press Attachment	490
(11) Drills	80	Uses of High Speed Steel, G. H. B.	420	Washers and Specialties, A Punch for the Manufacture of	470	Gang Milling of Repetition Castings	582
(12) Forming Tools and Milling Machine Cutters	190	Utilizing Niagara's Power at Night	553	"Washington, Geo.": Improved Drawing Table	437	Wopalezky, Eugene: Planing a Cross Groove	161
(13) Milling Machine Cutters	252	Vacation and What Came of It, A. A. P. Press	45	Water Connection for Car Wheel Press, Handy, A. E. Mitchell	443	Screw Cutting Kink	159
(14) Milling Machine Cutters	301	Vacuum System of Cleaning, Valentine, A. L.: Cutting English Threads with Metric Leadscrew	440	Water from Freezing or Souring, To Keep, W. T. Sears	444	Working of Sulphur Deposits at Calcasieu Parish, La.	477
Toolmaking, Notes on, Frank E. Shailor	210	Formula for Planing Thread Tools	489	Water Hammer in Steam Pipes	37	Works of the Ingersoll-Sergeant Drill Co., New	461
Tool-rest on American Lathes, Defective Design of	637	Value of a "Run of Stone" (H. & W. 9)	107	Water Supply from Ice Cap in Peru	639	Worm Gearing, An Example of, Oscar E. Perrigo	525
Tools for Facing Work in the Lathe, Robert A. Lachmann	160	Value of Photography	136	Water Pressure Maintained by Compressed Air	171	Worthington Pumping Engine, A	90
Tools, Modern Work With Ancient, E. J. Buchet	649	Valve, "Center Pressure" Stop	434	Waterproof Glued Joints, To W. S. Leonard	495	Write Black on Glass or Bright Metal, To, F. H. Jackson	444
Tool Steel Forging and Tempering, R. H. Henderson	67	Valve Disk Design to Prevent cutting	497	Water Space Watertube Boiler, Large	263	Y. M. C. A., Mechanical Courses at	137
Track Inspection Apparatus, Traction Wheels of Electric Motor Cars, Effect of	604	Valves Operated by Electric Motor	68	Water-tube Boilers for German Cruisers, G. L. F.	479	Zambesi River Bridge, The	144
Trade Mark Bill, New	366	Vanadium used in Electric Glow Lamp	603	Water Turbines, Bouvier Governor for, Dr. Alfred Gradenwitz	523	Zapote Tree	634
Trades and Faces	144					Zinc Black, Compound for Coating (H. & W. A to 16)	278
Transformer of High Voltage	24						

2
3
4
5
6
7
8
9
10
11
12
13
14
15
16
17
18
19
20
21
22
23
24
25
26
27
28
29
30
31
32
33
34
35
36
37
38
39
40
41
42
43
44
45
46
47
48
49
50
51
52
53
54
55
56
57
58
59
60
61
62
63
64
65
66
67
68
69
70
71
72
73
74
75
76
77
78
79
80
81
82
83
84
85
86
87
88
89
90
91
92
93
94
95
96
97
98
99
100